

Voltage input

Input

Power distribution

C. Pry the metal lock off the rail with screwdriver as arrow shown, pull downward the springs, and rotate the devices.

D. Remove the devices as arrow shows.

○ As far as possible to as possible